

Proposed Code Change State Form 41186R

RETURN TO: INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 W. Washington Street Room W246 Indianapolis, IN 46204

Code 50.10.10-09

FOR OFFICE USE ONLY

Received 7/17/09

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY – Dashed line through material to be deleted, underline material to be added)

Use second sheet for any material requiring more space.

Code Title		Edition
2009 Indiana Residential Code		First Edition
Section number and title		Page
R609.4.1 Construction, Item #4		1 of 1
Proponent	Title	
Craig Wagner	Chief Building Inspect	or/ IABO Code Comm. Member
Address		Phone
220 W Van Buren St, Columbia City IN 46725		260-248-3111
PROPOSED CODE CHANGE (Check One)		
R609.4.1. Construction. (Item #4 only) 4. Cells containing reinforcement shall be filled solidly with grout. Grout shall be poured in lifts of 8-foot (2438 mm) maximum height. When a total grout pour exceeds 8 feet (2438 mm) in height, the grout shall be placed in lifts not exceeding 5 feet (1524 mm) and special inspection during grouting shall be required.		
REASON AND FI	SCAL IMPACT	
REASON AND FI	SCAL IMPACT	
This proposal is brought forward from the 200 special inspection during grout pours.		s the requirement for
This proposal is brought forward from the 200 special inspection during grout pours.	05 InRC and remove	s the requirement for
This proposal is brought forward from the 200	05 InRC and remove	s the requirement for
This proposal is brought forward from the 200 special inspection during grout pours.	05 InRC and remove	s the requirement for
This proposal is brought forward from the 200 special inspection during grout pours. Fiscal impact: there is no increase to the continuous description.	05 InRC and remove	s the requirement for
This proposal is brought forward from the 200 special inspection during grout pours. Fiscal impact: there is no increase to the connection of the connectio	05 InRC and remove	s the requirement for
This proposal is brought forward from the 200 special inspection during grout pours. Fiscal impact: there is no increase to the connection of the connectio	05 InRC and remove	s the requirement for